

# Vesrah Clutch Cover Gaskets

## Kawasaki Street

Model	Year	Vesrah Ref	Order No.
ZL1000A1 Eliminator	1987	VL-4014	<b>643-4014</b>
ZX1000A1/A2 Ninja 1000R	86-87	VL-4014	<b>643-4014</b>
ZX1000B1/B2/B3 Ninja ZX-10	88-90	VL-4014	<b>643-4014</b>
KZ1100A1/A2/A3 Shaft	81-83	VL-4004	<b>643-4004</b>
KZ1100B1/B2 GPz	81-82	VL-4004	<b>643-4004</b>
KZ1100D1/D2 Spectre	82-83	VL-4004	<b>643-4004</b>
KZ1100L1 LTD	1983	VL-4004	<b>643-4004</b>
ZN1100B1/B2 LTD	84-85	VL-4004	<b>643-4004</b>
ZR1100C3/C4 ZRX1100	99-00	VL-4014	<b>643-4014</b>
ZX1100A1/A2 GPz	83-84	VL-4004	<b>643-4004</b>
ZX1100C1/C2/C3/C4 Ninja ZX-11	90-93	VL-4014	<b>643-4014</b>
ZX1100D1-D9 Ninja ZX-11	93-01	VL-4014	<b>643-4014</b>
ZX1100E1/E2/E3 GPz	95-97	VL-4014	<b>643-4014</b>
ZX1100F1 GPz (ABS)	1996	VL-4014	<b>643-4014</b>
ZG1200A1 Voyager XII	1986	VL-4051	<b>643-4051</b>
ZG1200B1-B17 Voyager XII	87-03	VL-4051	<b>643-4051</b>
ZR1200A1/A2/A3/A4/A5 ZRX1200	01-05	VL-4054	<b>643-4054</b>
ZX1200C1/C2/C3/C4 ZZR1200	02-05	VL-4054	<b>643-4054</b>

## Kawasaki ATV

KLF220A1-A15 Bayou 220	88-02	VL-4042	<b>643-4042</b>
KLF250A1/A2/A3/A6F/A7F Bayou	03-07	VL-4042	<b>643-4042</b>
KSF250A1-A17 Mojave	87-03	VL-4040	<b>643-4040</b>
KSF250A18 KFX250 Mojave	2004	VL-4040	<b>643-4040</b>
KXT250A1/A2 Tecate 3	84-85	VL-4012	<b>643-4012</b>
KXT250B1/B2 Tecate 3	86-87	VL-4030	<b>643-4030</b>
KEF300A1-A6 Lakota 300	95-00	VL-4036	<b>643-4036</b>
KEF300B1/B2/B3 Lakota Sport	01-03	VL-4036	<b>643-4036</b>
KLF300A1/A2 Bayou 300	86-87	VL-4036	<b>643-4036</b>
KLF300B1-B17 Bayou 300	88-04	VL-4036	<b>643-4036</b>
KLF300C1-C16 Bayou 300 4x4	89-04	VL-4043	<b>643-4043</b>

## Kawasaki Dual Sport & Offroad

KX60A1/A2	83-84	VL-4020	<b>643-4020</b>
KX60B1-B19	85-03	VL-4020	<b>643-4020</b>
KDX80B2/B3	82-83	VL-4020	<b>643-4020</b>
KDX80C1/C2/C3/C4/C5	84-88	VL-4020	<b>643-4020</b>
KX80C1/C2	81-82	VL-4020	<b>643-4020</b>
KX80E1/E2/E3	83-85	VL-4020	<b>643-4020</b>
KX80G1/G2	86-87	VL-4032	<b>643-4032</b>
KX80J2	1987	VL-4032	<b>643-4032</b>
KX80L1/L2/L3	88-90	VL-4032	<b>643-4032</b>
KX80N1/N2/N3	88 90	VL-4032	<b>643-4032</b>
KX80R1/R2/R3/R4/R5/R6/R7	91-97	VL-4032	<b>643-4032</b>
KX80T1/T2/T3/T4	91-94	VL-4032	<b>643-4032</b>
KX80W1/W2/W3 (inner)	98-00	VL-4032	<b>643-4032</b>
KX85A1/A2/A3/A4/A5 (inner)	01-05	VL-4032	<b>643-4032</b>
KX85A6F/A7F (inner)	06-07	VL-4032	<b>643-4032</b>
KX100B5/B6/B7	95-97	VL-4032	<b>643-4032</b>
KX100C1/C2/C3 (inner)	98-00	VL-4032	<b>643-4032</b>
KX100D1/D2/D3/D4/D5 (inner)	01-05	VL-4032	<b>643-4032</b>
KX100D6F/D7F (inner)	06-07	VL-4032	<b>643-4032</b>
KX125F1/G1	88-89	VL-4046	<b>643-4046</b>
KX125H1/H2	90-91	VL-4046	<b>643-4046</b>
KX125K1/K2/K3/K4/K5 (inner)	94-98	VL-4055	<b>643-4055</b>
KX125L1/L2/L3/L4 (inner)	99-02	VL-4055	<b>643-4055</b>
KDX200C1/C2/C3	86-88	VL-4037	<b>643-4037</b>
KDX200H1-H11	95-05	VL-4037	<b>643-4037</b>
KDX200H6F	2006	VL-4037	<b>643-4037</b>
KDX220A4-A12	97-05	VL-4037	<b>643-4037</b>
KX250D1/D2	85-86	VL-4030	<b>643-4030</b>
KX250E1/F1/G1/H1/H2 (inner)	87-91	VL-4049	<b>643-4049</b>
KX250K1/K2/K3/K4/K5 (inner)	94-98	VL-4056	<b>643-4056</b>
KX250K1/K2/K3/K4/K5 (outer)	94-98	VL-4057	<b>643-4057</b>
KX250L1/L2/L3/L4 (inner)	99-02	VL-4056	<b>643-4056</b>
KX250L1/L2/L3/L4 (outer)	99-02	VL-4057	<b>643-4057</b>
KX250M1/M2 (inner)	03-04	VL-4056	<b>643-4056</b>
KX250M1/M2 (outer)	03-04	VL-4057	<b>643-4057</b>

## Kawasaki Dual Sport & Offroad

Model	Year	Vesrah Ref	Order No.
KX500B1/C1/D1	86-88	VL-4034	<b>643-4034</b>
KX500E1-E16	89-04	VL-4034	<b>643-4034</b>
KL600A1 KLR600	1984	VL-4013	<b>643-4013</b>
KL600B1/B2 KLR600	85-86	VL-4013	<b>643-4013</b>
KL650A10-A19 KLR650	87-05	VL-4013	<b>643-4013</b>
KL650A6F/A7F KLR650	06-07	VL-4013	<b>643-4013</b>
KL650B2/B3 Tengai KLR650	90-91	VL-4013	<b>643-4013</b>

## Suzuki Street

GS450ET/EX/EZ/ED	80-83	VL-3006	<b>643-3006</b>
GS450LT/LX/LZ/LD	80-83	VL-3006	<b>643-3006</b>
GS450LF/LG/LH/LJ	85-88	VL-3006	<b>643-3006</b>
GS450ST/SX	80-81	VL-3006	<b>643-3006</b>
GS450TX/TZ	81-82	VL-3006	<b>643-3006</b>
GS450TX/TZ/TXZ/TXD	81-83	VL-3006	<b>643-3006</b>
GS500EK-EY	89-00	VL-3006	<b>643-3006</b>
GS500EK1/EK2	01-02	VL-3006	<b>643-3006</b>
GS500FK4/FK5/FK6/FK7	04-07	VL-3006	<b>643-3006</b>
GSF600ST-SK3 Bandit	96-03	VL-3039	<b>643-3039</b>
GSX600FJ-FK6 Katana	88-06	VL-3039	<b>643-3039</b>
GSX-R600WN/WP	92-93	VL-3070	<b>643-3070</b>
RF600RR/RS/RT	94-96	VL-3070	<b>643-3070</b>
GS700EF/ESF	1985	VL-3016	<b>643-3016</b>
GS750B/C/EC/N/EN/LN	77-79	VL-3001	<b>643-3001</b>
GS750ET/EX/EZ	80-83	VL-3007	<b>643-3007</b>
GS750ED/ESD	1983	VL-3016	<b>643-3016</b>
GS750LT/LX	80-81	VL-3007	<b>643-3007</b>
GS750SD Katana	1983	VL-3007	<b>643-3007</b>
GS750TZ/TD	82-83	VL-3007	<b>643-3007</b>
GSX750FK-FK5 Katana	89-05	VL-3039	<b>643-3039</b>
GSX-R750G/H/J/K/L/M/N	86-92	VL-3039	<b>643-3039</b>
GSX-R750RG	1986	VL-3039	<b>643-3039</b>
GSX-R750WP/WR/WS	93-95	VL-3070	<b>643-3070</b>
VS800GLN-GLK4 Intruder	92-04	VL-3065	<b>643-3065</b>
VS800 Boulevard S50	05-06	VL-3065	<b>643-3065</b>
VX800L/M/N/P	90-93	VL-3065	<b>643-3065</b>
GS850GN/GT/GLT/GX/GLX	79-81	VL-3001	<b>643-3001</b>
GS850GZ/GLZ/GD/GLD	82-83	VL-3009	<b>643-3009</b>
RF900RR/RS/RZS/RT/RV//	94-97	VL-3070	<b>643-3070</b>
GS1000C/EC/N	78-79	VL-3002	<b>643-3002</b>
GS1000EN/ET	80-81	VL-3002	<b>643-3002</b>
GS1000GT/GX/GZ/GD	80-83	VL-3009	<b>643-3009</b>
GS1000GLT/GLX/GLZ/GLD	80-83	VL-3009	<b>643-3009</b>
GS1000LN	1979	VL-3009	<b>643-3009</b>
GS1000SN/ST	79-80	VL-3002	<b>643-3002</b>
GS1000SZ Katana	1983	VL-3008	<b>643-3008</b>
GS1100ET/EX/EZ/ED/ESD	80-83	VL-3008	<b>643-3008</b>
GS1100GKZ/GK2/GKD/GKE	82-84	VL-3009	<b>643-3009</b>
GS1100LT	1980	VL-3008	<b>643-3008</b>
GS1100SD Katana	1983	VL-3008	<b>643-3008</b>
GSX1100FJ-FP Katana	88-93	VL-3039	<b>643-3039</b>
GSX1100GM/GN/GP Shaft	91-93	VL-3039	<b>643-3039</b>
GSX-R1100G/H/J/K/L/M/N	86-92	VL-3039	<b>643-3039</b>
GSX-R1100WP/WR/WS/WT/WV/WWW	93-98	VL-3070	<b>643-3070</b>
GS1150ES3/EF/EF2/ESE/ESF	83-85	VL-3008	<b>643-3008</b>
GS1150EG/ESG	1986	VL-3008	<b>643-3008</b>
GSF1200SVSW/SX/SY Bandit	97-00	VL-3039	<b>643-3039</b>
GSF1200SAV Bandit	1997	VL-3039	<b>643-3039</b>
GSF1200SK1-SK5 Bandit	01-05	VL-3039	<b>643-3039</b>
VS1400GLPH-GLPY Intruder	87-00	VL-3066	<b>640-3066</b>
VS1400GLPK1-GLPK4 Intruder	01-04	VL-3066	<b>640-3066</b>
VS1400 Boulevard S83	05-06	VL-3066	<b>640-3066</b>
VL1500W-K4 Intruder 1500 LC	98-04	VL-3066	<b>640-3066</b>

## Suzuki ATV

LT80H-Y Quadrunner	87-00	VL-3056	<b>643-3040</b>
LT80K1/K2/K3/K4 Quadport	01-04	VL-3056	<b>643-3040</b>
LT160EK/EL/EM/EN	89-92	VL-3033	<b>643-3033</b>